	B100	×	_ ran	DEI NO	_
1	Safety	Assessme	nt F	orm	

ATC-20 Detailed Evaluation So	dety Assessment Form
BUILDING DESCRIPTION; Name: Destartion Building Address: 20016 WA	OVERALL RATING: (Check One) INSPECTED (Green) LIMITED ENTRY (Yellow) UNSAFE (Red)
No. of Stories:	INSPECTOR: Inspector ID
Structural System: Wood Frame   Unreinforced Masonry   Reinforced Masonry   Concrete Frame   Concrete Shear Wall   Steel Frame   Other	INSPECTION DATE:  Mo/day/year planch / though Harch 5  Timeall. +ime8arm pm
Primary Occupancy: Dwelling  Other Residential  Commercial Office  Industrial Public Assembly  School Government  Emer. Serv. Historic Other	
Instructions: Complete building evaluation and check results below.	list on next page and then summarize

results below.			
Posting:	Existing	Recommended	
None	o -		Posted at this Assessment:
Inspected (Green)	П	₩.	☑ Yes □ No
Limited Entry (Yellow)	፟	ñ	Existing posting by:
Unsafe (Red)	õ		Seattle DCLU

Recor	nmendatio	ms:	
	No further	action	re

☐ Engineering Evaluation required (circle one) Structus
☐ Barricades needed in the following areas:

Other (falling hazard removal, shoring/bracing required, etc.):

Comments (Why posted Unsafe, etc.): for structural evalual review, response of anaeked glaster

## ATC-20 Detailed Evaluation Safety Assessment Form (Continued)

Instructions: Examine the building to determine if any hazardous conditions exist. A "yes" answer in categories 1, 2, or 4 is grounds for posting building UNSAFE. If condition is suspected to be unsafe and more review is needed, check appropriate Unknown box(es) and post LIMITED ENTRY. A "yes" answer in category 3 requires posting and/or barricading to indicate AREA UNSAFE. Explain "Yes", "Unknown" findings and extent of damage under "Comments."

	Hazardous Condition Exists				
Condition	Yes	No	Unknown	Comments	
Structure Hazardous Overall Collapse/partial collapse Building or story leaning Other					
2. Hazardous Structural Elements Foundations Roof/floors (vertical loads) Columns/pilasters/corbels Diaphragms/horizontal bracing Walls/vertical bracing Moment frames Precast connections Other	00000000		00000000	Lick\$.	
3. Nonstructural Hazards Parapets/ornamentation Cladding/glazing Ceilings/light fixtures Interior walls/partitions Elevators Stairs/exits Electric/gas Other				by others  clean up in progress or complete clean up completed	
4. Geotechnical Hazards Slope failure/debris Ground movement, fissures Other					

SKETCH: